

5.8. 10/722,793 (B. Joe Kim) (312) 360-0080









COFFEE ROASTER HAVING AN APPARATUS...

Noon et al. S.N. 10/722,793
Greer, Burns 6 Crain, Ltd. (8. Joe Kim)
Ref. No. 0807.68722 (312) 160-0080
Raplacement Sheet 3 of 14





COFFEE ROASIER HAVING AN APPARATUS... 11/22/04 Moon et al. S.B. 10/722,793 Greer, Burns & Crain, Ltd. (B. Joe Kim) Ref. No. 0807.68722 (312) 360-0080 Replacement Sheet 5 of 14




FIG. 5

COFFEE ROASTER HAVING AN APPARATUS. 11/22/04
Moon et al. S.N. 10/722,793
Greer, Burns & Crain, Ltd. S.N. 10/722,793
Ref. No. 0807.68722 (312) 360-0080
Replacement Sheet 6 of 14




FIG. 6

COFFEE ROASTER HAVING AN APPARATUS... 11/22/04 moon et al. 5.N. 10/722,793 Greer, Burns 6 Crain, Ltd. (B. Joe Kial Ref. No. 0807.68722 (312) 360-0080 Replacement Sheet 7 of 14




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14